

BMW 428i xDrive Coupé Modern Line

03/2015, 180,026 km

Paint readings 04.11.2026, mileage as of 07.10.2026

Body	**2 of 9 measured panels repainted.** Front left wing, rear left quarter panel. The other 7 are within the factory paint range.
Remarks	6 items, 4 with photo
Work	Oil changes and a new front differential in October 2026.
History	Six records with mileage from the BMW report. Two records from 2020 differ by 1,800 km, the reason has not been established.

Vehicle data

First registration	Mileage	Power	Gearbox	Fuel
03/2015	180,026 km	180 kW · 245 hp	8-speed automatic	Petrol
Emission class	**Colour**	**Owners**	**Keys**	**Drivetrain**
Euro 6	Orion-Silber metallic	1	2	All-wheel drive (xDrive)

Built: Munich, 26.02.2015. The report lists no technical campaigns and no fault messages. Modern Line, Leather interior, Heated sports seats, Xenon, Navi Professional, HiFi, Cruise control with braking, Automatic climate control, Auto-dimming mirrors, Rain sensor, Styling 415 wheels, Tyre pressure monitoring, runflat, Through-loading system, Fineline Pur trim.

Paint per panel, measured on 04.11.2026

Diagram: right side




Diagram: from above, front to the left





Diagram: left side



Rear left quarter panel From 180 to 300 µm on this panel	Repainted	**300 µm**
Front left wing	Repainted	**180 µm**
Left door		**124 µm**
Bonnet		**122 µm**
Roof		**121 µm**
Front right wing		**112 µm**
Rear right quarter panel		**109 µm**
Boot lid		**108 µm**
Right door		**101 µm**

Not measured: bumpers, sills, pillars, mirrors.

Up to 160 µm within factory paint range. 161 to 300 repainted. Over 300 filler.

Front



Rear




Remarks

From above



Right side



Left side



The numbers on the diagram match the items below. Photos and lines without a number are not marked on the diagram.



1 **Dent in the right door**
Dent in the lower part of the door.



2 **Right rear quarter panel**
Damage to the panel below the right tail light.



4 **Front bumper, right**
Scratches on the corner of the bumper.



5 **Right sill**
Scratches with damaged paint.



Scratches at the wheel arch and at the panel joint.



Mark on the lower edge above the sill.

3 **Rear bumper, left**
Damage on the left. There is no photo of this spot.

6 **Dent on the bonnet**
Small dent in the middle of the bonnet, about the size of a 1 euro coin. There is no photo of this spot.

In places the paint is damaged down to the base.

Tyres
Summer tyres, tread about 6 mm. The tyres are old and the rubber has hardened.

Service and work

Work

05.10.2026 Engine oil, transfer case oil and rear differential oil changed.

06.10.2026 New front differential fitted with new oil.

07.10.2026 Test drive without findings. Interior detailed, non-smoker.

We do a new inspection (HU) before handover.

Timing chain: no records, no findings.

From the car's display

Engine oil	05/2028 or in 23,000 km
Brake fluid	05/2028
Front brake pads	in 28,000 km
Rear brake pads	in 45,000 km

Vehicle history from records

09.03.2015	First registration, warranty start	
10.10.2016	Service record The record says: service overdue by 14,000 km.	40,510 km
16.10.2019	Service record	94,982 km
19.11.2020	Service record	109,309 km
03.12.2020	Service record The mileage in this record is lower than in the record two weeks earlier. The reason for the difference has not been established.	107,509 km
25.01.2023	Service record	132,831 km
18.09.2024	Mileage read from the key	155,735 km
07.10.2026	Odometer reading 	180,026 km

Records and factory data from the BMW report of 15.10.2026. The report does not say what was done at each service.